Safety information for the EDA 1200 sensor

Published: 2024-08-06

This document provides safety compliance information for the EDA 1200 sensor.

Safety and installation instructions

- 1. Do not open or modify the device. The device has been tested and complies with FCC and CE regulations. Modification of the device will void these certifications.
- 2. Install the device securely. Be careful handling the device to prevent injury and do not drop.
- 3. Operational temperature must be between 0-40° C with a relative, non-condensing humidity of 0-90%. The device can be stored at temperatures between 0-60° C.
- 4. Keep the device away from liquids and flammable materials.
- 5. Do not clean the device with liquids. The chassis can be cleaned with a cloth.
- 6. Allow at least 2 inches of space around all sides of the device for proper cooling.
- 7. This device is intended for indoor operation only.
- 8. Install this device only with the supplied AC power adapter. Ensure proper voltage and current ratings of the power supply.
- 9. Install the device only with shielded network cables.
- 10. Install molded ferrite filtered DisplayPort cables only, such as Monoprice P/N 12001 or equivalent.
- 11. Service and repair of the device must be done by qualified service personnel.

Warning: There is danger of explosion if the CMOS battery is replaced incorrectly.